

Service Report



Report Header Information

Work Order	110040220	Dealer Code	J261	Manufacturer	Caterpillar Inc.
Employee ID	9954	Service Date	7/4/2017	Model	3516
Customer	TURBO SERVICES	Customer Equipment Number		Customer PO	
Serial Number	SSP00195				
SMU	1 Hours	Equipment Location	PORT KLANG FREE ZONE (PKFZ)		
IN Date		Promise Date		OUT Date	
Instructions	TO CARRY OUT GENSET VISUAL INSPECTION & DOWNLOAD ECM HISTORY DATA				

Repair Background

Segment No:	01:
Customer Complaint	Request Tractors Malaysia to verify Gensets new/unused.
Cause of Failure	None.
Resultant Damage	None.
Repair Process Comments	<p>SCOPE OF WORKS:</p> <p>1) TO CARRY OUT TA1 VISUAL INSPECTION TO ASSESS ENGINE CONDITION</p> <p>2) CONFIRM ENGINE SERIAL NUMBER & SMU</p> <p>3) HOOK UP TO ET LAPTOP AND DOWNLOAD STATUS REPORT</p> <p>4) TO OPEN UP ENGINE SIDE COVER AND INSPECT INTERNAL COMPONENTS</p> <p>.</p> <p>ENGINE WILL NOT BE START UP AND ANY DEFECTS OR FAULTS UPON STARTING UP WILL NOT BE CONFIRMED DURING THIS EXERCISE</p>

Customer Signature	Technician Signature
--------------------	----------------------

File Attachments

Name	Size	Modified	Title	Description
SAM_3561.JPG	2184657	7/4/2017 2:37 PM	ENGINE S/N PLATE	
SAM_3578.JPG	2216378	7/4/2017 2:41 PM	GENERATOR S/N PLATE	
SAM_3565.JPG	2198375	7/4/2017 2:38 PM	GENSET STORED INDOOR	
SAM_3566.JPG	2237081	7/4/2017 2:38 PM		
SAM_3567.JPG	2277440	7/4/2017 2:38 PM		
SAM_3577.JPG	2267579	7/4/2017 2:40 PM		
SAM_3573.JPG	2246920	7/4/2017 2:40 PM		
SAM_3580.JPG	2231261	7/4/2017 2:41 PM		
SAM_3665.JPG	2195614	7/4/2017 3:31 PM	FROM SIDE COVER	
SAM_3667.JPG	2226490	7/4/2017 3:32 PM	FROM SIDE COVER	
SAM_3666.JPG	2187183	7/4/2017 3:31 PM	FROM SIDE COVER	

Title: ENGINE S/N PLATE

7/4/2017 2:37 PM

Description:



Title: GENERATOR S/N PLATE

7/4/2017 2:41 PM

Description:



Title: GENSET STORED INDOOR

7/4/2017 2:38 PM

Description:



Title:
7/4/2017 2:38 PM
Description:



Title:
7/4/2017 2:38 PM
Description:



Title:
7/4/2017 2:40 PM
Description:

Title:
7/4/2017 2:40 PM
Description:

Title:
7/4/2017 2:41 PM
Description:



Title: FROM SIDE COVER

7/4/2017 3:31 PM


Description:



Title: FROM SIDE COVER

7/4/2017 3:32 PM

Description:



Title: FROM SIDE COVER

7/4/2017 3:31 PM

Description:

